## Chrysler 3.6 Pentastar Value Added Quality Improvements from JASPER

#### Issue / Concern: **JASPER Solution:** Rocker and Camshaft Failure 100% installation of NEW late-design rockers/cam followers, improving longevity of the bearing assembly in the rocker. Engine Misfire 100% replacement of early-style cylinder head valve seats with copper-• (Dropped Valve Seats, infiltrated seats for improved heat dissipation and reduced wear. and Valve Guide Wear) 100% installation of NEW nitrided valves for improved heat resistance and • reduced valve guide wear. **Rod Bearing Failure** 100% installation of high-strength, Class 12.9 rod bolts to eliminate stretching, which can lead to bearing failure. Dry Start-Up and Piston Scuffing JASPER-designed piston with graphite coating helps prevent dry start-up and • piston scuffing. JASPER-designed pistons include 28% more major thrust bearing area to prevent dry start-up and piston scuffing. Oil Consumption Stronger JASPER-engineered pistons have a smooth, fully-machined, • anodized crown which provides a thermal barrier and reduces carbon buildup.

- JASPER's piston design includes additional oil return holes (12 total) for increased oil drainback, to reduce oil consumption and prevent the oil rings from sticking.
- JASPER installs a robust, two-piece 2.0mm oil ring for improved oil control.
- JASPER piston rings include a steel top ring that has a PVD and DLC coating for longevity and less friction.
- Additional accumulator groove is machined into the piston to decrease the pressure between the first and second ring land, preventing the upper (compression) ring from unseating at higher RPMs.
- 100% installation of synthetic, rubber-based PTFE (polytetrafluoroethylene) valve stem seals.

## 3 Year/100,000 Mile Nationwide Parts & Labor Warranty

Full warranty disclosure available at www.jasperengines.com or upon request. Specifications subject to change without notice.



### Remanufactured in the U.S.A.

815 Wernsing Road • P.O. Box 650 • Jasper, IN 47547-0650 (800) 827-7455 • Fax (812) 634-1820 • www.jasperengines.com

# **Chrysler 3.6 Pentastar** Value Added Quality Improvements from **JASPER**

Piston Slap	<ul> <li>100% torque plate honing of engine block, utilizing a torque plate and specially-designed, ARP2000<sup>®</sup> bolts, provides cylinder wall geometry that matches the cylinder head as a complete running assembly, for improved ring sealing.</li> <li>JASPER-designed pistons include 20% more pin bearing area for better stability.</li> </ul>
Head Gasket Failure	<ul> <li>Installation of JASPER-designed pins in the block, which lock the cylinders together under heavy load. This prevents the cylinders from moving, which can lead to head gasket scuffing, a common cause of failure.</li> <li>Block is CNC machined for 100% installation of steel threaded inserts for head bolts, increasing strength over the original aluminum design that pull out.</li> <li>Upgraded D-shaped head gaskets increase fire ring pressure for improved sealing under heavy use.</li> <li>JASPER installs a thicker, PTFE (polytetrafluoroethylene) coated MLS (Multilayer steel) head gasket.</li> <li>Block and heads are resurfaced to a 50–150 Rz finish.</li> </ul>
Engine Oil Contamination	<ul> <li>100% installation of NEW engine oil cooler, and for ease of installation, assembly includes: oil temperature sensor, oil pressure sensor, knock sensor, and adapter harness.</li> </ul>
Low Oil Pressure	<ul> <li>100% of the Chrysler 3.6L remanufactured oil pumps are tested on state-of- the-art, JASPER designed, stand-alone oil pump testing equipment. Oil pressure and flow are measured with solenoid on and off throughout a full RPM sweep of the remanufacture oil pump operating range.</li> </ul>
VVT Failure	• VVT's are hydraulically tested using a state-of-the-art oil-controlled, test stand.
Reliability	<ul> <li>100% live-run tested to verify proper compression, vacuum and oil pressure.</li> <li>100% tested intake and exhaust cam actuators to verify proper performance.</li> <li>100% black light leak tested to ensure the unit is leak free.</li> </ul>

100% black light leak tested to ensure the unit is leak free.

### 3 Year/100,000 Mile **Nationwide** Parts & Labor Warranty

Full warranty disclosure available at www.jasperengines.com or upon request. Specifications subject to change without notice.



### Remanufactured in the U.S.A.

815 Wernsing Road • P.O. Box 650 • Jasper, IN 47547-0650 (800) 827-7455 • Fax (812) 634-1820 • www.jasperengines.com